

Operating manual CO₂ Logger

EN

CDL 210



Best.-Nr. 22412 – 2012-10-08

Contents

1	General Information	32
1.1	Operation Manual Information	32
1.2	Notes	32
1.3	Intended use	32
1.4	Components	32
1.5	Information on disposal	33
1.6	Adresse	33
2	Specifications	34
3	Component explanation	36
3.1	Keys	36
3.2	Display	37
4	Operation	38
4.1	Power on/off	38
4.2	Taking Measurement (CO ₂ , temperature and humidity)	39
4.3	MAX, MIN	39
4.4	Data logging	40
4.5	Data Transmission	41
5	Alarm	42
5.1	Setting the alarm	42
5.2	Alarm indicator	42
6	Setup	43
6.1	Enter and exit setup mode	44
6.2	Setting the CO ₂ upper limit of good level	44
6.3	Setting the CO ₂ upper limit of NORMAL level	44
6.4	Setting the CO ₂ alarm limit	45
6.5	Switching the alarm beep on and off	46
6.6	Temperature scale	46
6.7	Clock and calendar	47
6.8	Reset	49
6.9	Sampling Rate	50
7	CO₂-Calibration	50

7.1	Automatic Baseline Calibration	51
7.2	Manual Calibration	51
8	Trouble shooting	52
9	Error Code	52
9.1	CO ₂ -Werte	52
9.2	Air Temperature Readings.....	53
9.3	Air Humidity Reading	53
10	Warranty and Service	54
10.1	Warranty	54
10.2	Service.....	54
11	Declaration of Conformity	54

1 General Information

1.1 Operation Manual Information

This operation manual allows you to safely work with the Wöhler CDL 210 CO₂ Logger. Please keep this manual for your information.

The Wöhler CDL 210 should be used by trained professionals for its intended use only.

Liability is void for any damages caused by not following this manual.

1.2 Notes



WARNING!

Not following this warning can cause injury or death.



ATTENTION!

Not following this note can cause permanent damage to the analyzer.



NOTE!

Useful information


1.3 Intended use

The Wöhler CO₂-logger measures the CO₂ level, the air temperature and the humidity and logs the measured data. It is therefore ideal for the monitoring and the evaluation of the interior climate in living spaces and in commercial premises.

1.4 Components

Model	Parts
Wöhler CDL 210	CO ₂ -Logger
	Power supply
	USB cable
	Software

1.5 Information on disposal



Electronic equipment does not belong into domestic waste, but must be disposed in accordance with the applicable statutory provisions.

You may hand in any defective batteries taken out of the unit to our company as well as to recycling places of public disposal systems or to selling points of new batteries or storage batteries.



1.6 Adresse

PCE Deutschland GmbH

Im Langel 4

59872 Meschede

Tel.: +49 2903 976 990

Fax: +49 2903 976 9929

E-Mail: info@pce-instruments.com

Service-Hotline:

+49 2903 976 990

2 Specifications

CO₂-Measurement

Description	Data
Range	0 – 2.000 ppm (2001 - 9.999 ppm out of scale range)
Resolution	1 ppm
Accuracy	± 50 ppm ± 5 % of reading (0-2000 ppm)
Pressure dependence	± 1,6 % of reading per kPa deviation from normal pressure, 100 kPa
Sensor	Stable NDIR sensor

Temperature

Description	Data
Range	-10 °C to +60 °C
Resolution	0,1 °C (0,1 °F)
Accuracy	± 0,6 °C (± 0,9 °F)

Relative Humidity

Description	Data
Range	5 – 95 %
Resolution	0,1 %
Accuracy	± 3 % (10 – 90 %, 25 °C), 5 % (other values, 25 °C)

Data Logging

Description	Data
Number of measurement series	5.333 per reading (°C, %rF, CO ₂)
Data logging	15.999
Sampling rate	from 1 second to 4:59:59 hours

EN

General technical data

Description	Data
Display	Simultaneous indication of CO ₂ level, temperature and relative humidity
Indoor air quality indication	Good Normal Poor
Power Supply	AC Adapter 5 V, 0,5 A output
Connection to PC	USB-interface
Dimensions (L x B X D)	120 mm x 100 mm x 110 mm
Visible and audible CO ₂ warning alarm.	

3 Component explanation

3.1 Keys



Fig. 1: Component explanation

Number	Key	Function
1	SET	Enter setup mode Save and finish settings
2	ESC	Exit setup mode Exit data logging mode Terminate datalogging Terminate calibration
3	RESET	Clear MAX/MIN records
4	LOG/▲	Start data logging Select mode Increase value in setup mode
5	MIN/MAX▼	Activate MIN/MAX function Select mode Decrease value in setup mode
1 + 4 + 5	Set + ▲ + ▼ (Press simultaneously)	CO ₂ - calibration

3.2

Display





Fig. 2: Display details

Icon	Signification
MIN/MAX	Minimum/Maximum readings
GOOD	Good CO ₂ level
NORMAL	Normal CO ₂ level
POOR	Poor CO ₂ level
Air Temp.	Air temperature
Humidity %	Unit of relative humidity (air)
	Relay activated CO ₂ alarm

4 Operation

4.1 Power on/off

! ACHTUNG!

Calibrate the Wöhler CDL 210 at fresh air, before using it for the first time (see chapter 7).

Plug in the power supply and the meter turns on automatically with a short beep. The readings will immediately appear in the display.

! ATTENTION!

If the voltage is too high or low, "bAT" will flash in the display. (Please see chapter 8 "Trouble shooting").

! WARNING!

Risk of electrical shock!

Never touch the jack with wet hands!

Protect the power supply against water and moisture!

Do not unplug the power supply by pulling the cable!

Do not use the power supply when the voltage requirements of the recharger and the supply do not match!




Fig. 3: Initial display

The display will show the current CO₂-value, the temperature, humidity, date and time.

The air quality level is indicated as good, normal or poor, see Fig. 3.

4.2 Taking Measurement (CO₂, temperature and humidity)

The Wöhler CDL 210 starts taking measurement after it has been turned on and updates readings every second.

If the operating environment changes (ex. from high to low temperature), it will take 2 minutes until the correct CO₂ and temperature readings are indicated and 10 minutes until the correct relative humidity is indicated.



NOTE!

Do not hold the meter close to faces, because the exhalation can affect the CO₂ level.

4.3 MAX, MIN




Fig. 4: Minimal value

- In normal operation mode, press MIN/MAX ▼ to see the minimum or maximum of each parameter. With each press of the MIN/MAX ▼-key in sequence, the display shows the MINIMUM, then the MAXIMUM and after that it returns to the normal mode.
- In MIN and MAX modes, it shows the minimum and maximum readings of CO₂ on the main display and the air temperature and the humidity on the lower display. (Fig. 4)

In MIN/MAX or normal operation modes, press and hold RESET for more than 1 second to clear the minimum and the maximum value and then restart. After that the device will calculate new minimal and maximal values.



NOTE!

You can carry out this step in MIN/MAX and normal operation mode.

4.4 Data logging

The Wöhler CDL 210 can record readings of CO₂, temperature and humidity for long time environment monitoring. The memory capacity is 16 000 points.

The user can set up the sampling rate from 1 second to 4:59:59 hours. (The corresponding steps are explained in chapter 6.9 “Sampling rate”).

- After the sampling rate is selected, press LOG/▲ for 2 seconds in normal mode to start logging.

The green LED light blinks to indicate the logging status and the main display shows the current CO₂ value and “rEC” in turn. Lower displays are the current temperature, humidity and clock.

- To terminate the data logging, press ESC for 2 seconds.

The green LED light stops blinking and the main display shows “End” and the CO₂ reading in turn.

- Press and hold ESC for 2 seconds again, and it returns to normal measurement mode.



NOTE!

Minimum and Maximum recall is still working during logging.



NOTE!

The CDL 210 will stop logging during a power breakdown. After the power breakdown it will continue logging because the internal battery has provided power to the clock during the breakdown (see note in fig. 6.7) The graph of the PC software will present a gap for the breakdown time.

4.5 Data Transmission



Fig. 5: Rear side of the Wöhler CDL 210 with USB cable and power supply

After that, the logged data can be transferred to the computer via the USB-cable for detailed analysis with the PC Software Wöhler CDL 210.

- Insert the plug of the USB cable into the socket of the rear side of the Wöhler CDL 210.
- Insert the USB plug into the USB interface of your PC.



NOTE!

For information about the transmission of the data to the computer and the application of the software, see Manual PC-Software Wöhler CDL 210 (art n° 22413) delivered with the software CD.

For information about the installation of the USB driver, see Manual USB transmission cable. (art. n° 22354)

All manuals are also provided as a download in internet (<http://mgkg.woehler.de>).

5 Alarm

5.1 Setting the alarm The meter features audible alarm to give warnings when CO₂ concentration exceeds the limits. Users can set up 2 limits:

1. Limit for alarm threshold that requires ventilation.
2. Lower limit: The ventilation system has to be stopped, when this limit is reached.

- Set the limits according to chapter 6.4.

5.2 Alarm indicator




Fig. 6: Alarm display

The CDL 210 emits beeps (80 dB) and a fan icon will appear on the display, when the CO₂ level exceeds the upper limit.

- Beeps can be stopped by pressing any key or it automatically stops when the CO₂ reading falls under the lower limit. The icon keeps flashing after the beeps have been manually shut.
- Users can press RESET for more than 1 second to reactivate the alarm.

If the beep is temporarily shut, it will sound again, when the readings fall under the lower limit and then exceed the upper limit again.

6 Setup

In the different modes of the Wöhler CDL 210, different parameters can be set.

Mode	Parameter
P1.1	CO ₂ limit for good interior air quality
P1.2	CO ₂ limit for normal interior air quality
P1.3	CO ₂ beep alarm
P1.4	CO ₂ beep alarm on/off
P2.0	temperature scale
P3.1	year
P3.2	month
P3.3	day
P3.4	12 hour or 24 hour display
P3.5	hour
P3.6	minute
P4.0	reset
P5.1	lograte: hours
P5.2	lograte: minutes
P5.3	lograte: seconds

Press and hold SET for 3 seconds to enter the setup mode. Press LOG to change from P1.0 to P2.0 and the SET to change from P 1.1 to P1.2 etc. The following chapters 6.1 to 6.8 will describe the parameters in detail.

6.1 Enter and exit setup mode

- Press and hold SET under normal mode for more than 3 seconds to enter the setup mode.
- To exit setup mode, press ESC.

6.2 Setting the CO₂ upper limit of good level

In the setup mode, CO₂ and P 1.0 are displayed. (see Abb. 7)

- Press SET again to enter the P1.1 mode for setting the CO₂ upper limit of GOOD level.



Fig. 7: Setting P1.0: good level




Fig. 8: Setting the upper limit of the good level.

The current set value is blinking now (see Abb. 8).

- Press LOG/▲ to increase or MIN/MAX▼ to decrease the value.

Each press tunes 100 ppm.



NOTE!

The alarm range is from 0 to 700 ppm.

- Press SET again to confirm the P 1.1 setting and to enter the P 1.2 mode for the upper limit of NORMAL level.

Press ESC (without pressing SET before) to return to P 1.0 without saving.

6.3 Setting the CO₂ upper limit of NORMAL level

- Press LOG/▲ to increase or MIN/MAX▼ to decrease the value.

Each press tunes 100 ppm.



NOTE!

The alarm range is from 700 ppm to 1000 ppm.




Fig. 9: Setting the CO₂ upper limit of NORMAL level

Press ESC (without pressing SET before) to return to P 1.0 without saving.

6.4 Setting the CO₂ alarm limit




Fig. 10: Setting the alarm limit

In the P 1.3 mode the current set value will be blinking and the flat icon will appear (see Abb. 10).

- Press LOG/▲ to increase or MIN/MAX▼ to decrease the value.

Each press tunes 100 ppm.



NOTE!

The alarm range is from 1000 ppm to 5000 ppm.

Press SET to confirm.



NOTE!

Set up the alarm value within the specification range, so that accuracy is ensured. Readings that are out of specification are only for reference and not suitable to be used as alarm limits.

6.5 Switching the alarm beep on and off

In the P 1.4 mode the alarm beep can be switched on and off.

- Select ON to activate the alarm beep.
- Select OFF to deactivate the alarm beep.
- Press SET to save the setting.

6.6 Temperature scale

Select the temperature unit in P2.0 mode. Go from normal mode to 2.0 mode by doing the following steps:



Fig. 11: Display P2.0-mode




Fig. 12: Selecting the temperature

- Press and hold SET in normal mode for three seconds to enter P1.0 mode.
- Press LOG/▲ in P1.0 mode to enter P2.0 mode (see Fig. 11).
- Press SET to enter P2.1 mode for setting the actual temperature unit with the actual unit °C or °F blinking (Fig. 12)
- Press LOG/▲ or MIN/MAX▼ key to change from °C to °F.
- Press SET to save the settings or press ESC to return to P2.0 mode without saving.

6.7 Clock and calendar




Fig. 13: Setting clock and calendar (rtc: real time clock)




Fig. 14: Setting the year

24 hour and 12 hour time displays are both available in this meter. Setting can be done in P3.0 mode.

Go from normal mode to P3.0 mode by doing the following steps:

- Press and hold SET in normal mode for three seconds to enter P1.0 mode.
- Press LOG/▲ in P1.0 mode twice to enter P3.0 mode for setting clock and calendar (Fig. 13).
- Press SET to enter P 3.1 mode. Current year will blink (Fig. 14). To change the month, press LOG/▲ or MIN/MAX▼.
- Press SET to save the settings and enter P3.2 mode or press ESC to return to P3.0 mode without saving.
- In P3.2 mode the current month will blink. To change the month press LOG/▲ or MIN/MAX▼.
- Press SET-key to save the settings and enter P3.3 mode or press ESC to return to P3.0 mode without saving.




Fig. 15: 12 hour or 24 hour display




Fig. 16: Setting the hour (clock)

- Repeat the steps described above for setting the date (day) in P3.3 mode. Press SET-key to save the settings and enter P3.4 mode or press ESC to return to P3.0 mode without saving.
- In P3.4 mode the current time setting (12 hour or 24 hour) will blink (Fig. 15). To change the setting press LOG/▲ or MIN/MAX▼.
- Press SET to save the settings and enter P3.5 mode to set the hours, Fig. 16. Press Set to save and enter P 3.6 mode to set the minutes or press ESC to return to P3.0 mode without saving.
- Repeat the steps described above and save your settings with the SET-key.



NOTE!

The CDL 210 has an internal rechargeable battery that provides power to the clock. It takes at least 24 hours to charge this battery with the power supply. In case of a voltage interruption, that is when the power supply is unplugged, the internal battery will provide power to the clock during 10 hours.

6.8 Reset




Fig. 17: Reset-mode




Fig. 18: no reset

- In normal mode press and hold the SET key for three seconds to enter P1.0 mode.
- Press LOG/▲ three times to enter P4.0 mode for reverting the meter to default status, see Fig. 17.
- Press SET to enter P4.1 mode with blinking “No” (default), see Fig. 18, so that no reset will be done.
- To switch the status (Display “YES”) press LOG/▲ or MIN/MAX▼. When “Yes” is chosen, y reset to the parameters specified above will be done.
- Then press SET to save the setting or press ESC without saving and return to P4.0 mode.

If you choose “Yes” the meter is reset to the following defaults:

Parameter	Default
P 1.1	700 ppm
P 1.2	1000 ppm
P 1.3	5000 ppm
P 2.1	°C
P 4.1	No (no reset)

6.9 Sampling Rate



Fig. 19: Setting the sampling rate (hours)



Fig.18

Fig. 20: Setting the sampling rate (seconds)

- In normal mode press and hold the SET key for three seconds to enter P1.0 mode.
- Press LOG/▲ four times to enter P 5.0 mode for setting the sampling rate of data logging, see Fig. 19.



NOTE!

The range is from 1 second to 4 hours 59 minutes and 59 seconds.

- Press SET to enter the 5.1 mode with the hour digits blinking. To change the setting press LOG/▲ or MIN/MAX▼.
- Press SET to enter P5.2 mode to set the minutes and after that enter the P5.3 mode to set the seconds, see Fig. 20. To change the setting press LOG/▲ or MIN/MAX▼.
- Then press SET to save the setting or press ESC without saving and return to P5.0 mode.

7 CO₂-Calibration

The meter is calibrated at standard 400 ppm CO₂ concentration in factory. It is suggested to do manual calibration regularly and especially before using it for the first time to maintain good accuracy. The calibration will last about 30 minutes.

When accuracy becomes a concern after a long time usage or other special conditions, return to dealers for standard calibration.



WARNING!

Do not calibrate the meter in the air with unknown CO₂ level. Otherwise, it will be taken as 400 ppm and this fact leads to inaccurate measurements.

7.1 Automatic Base-line Calibration

The automatic baseline calibration (ABC) eliminates the zero drift of the infrared sensor. The ABC function is always ON when turning on the meter.

ABC is to calibrate the meter at the minimum CO₂ reading detected during 7.5 days continuous monitoring (power on). It is supposed that in the ventilating area there is fresh air with CO₂ level around 400 ppm during a period of time.



WARNING!

For the described reasons, the automatic baseline calibration cannot be done in close area with higher CO₂ level such as places with windows shut.

7.2 Manual Calibration

The manual calibration is suggested to be done outdoor, e.g. on an exterior window ledge, on a sunny day where CO₂ level is around 400 ppm.



NOTE!

Do not calibrate on rainy days, because the high humidity will affect the CO₂ level in air.

Do not calibrate the meter in places crowded with people or close to where exist high CO₂ concentration such as ventilating outlets or fireplaces.




Fig. 21: Display during the CO₂ calibration

- Turn on the meter and hold down SET, LOG/▲ and MIN/MAX▼ simultaneously and more than 1 second to enter CO₂ calibration mode, Fig. 21.

400 ppm and CO₂ are blinking on the LCD while performing calibration, Fig. 21. Wait about 30 minutes until the blinking stops and the calibration is completed automatically. The meter will return to normal mode now.

To abort the calibration, press ESC for more than 1 second.

8 Trouble shooting

Error message	Possible reason	Solution
The meter cannot be powered on.	The power supply is not well plugged.	Check if the power supply is well plugged.
	System crash	Use a needle or toothpick to stab the RESET hole at the meter bottom.
The readings in the display do not change.	The meter is in maximum or minimum mode.	Press and hold the RESET key for more than one second.
“Bat” and the green LED keep flashing.	The power supply output voltage is too high or too low.	Use the adaptor with 5 V ($\pm 10\%$), > 0,5 A.
The data cannot be transferred from the Wöhler CDL 210 to the PC	Data transfer disturbed	Do a hardware reset: Press a paper clip (or similar) into the small opening in the middle of the bottom of the device.

9 Error Code

9.1 CO₂-Werte

Error Code	Problem	Solution
E01	CO ₂ -sensor is damaged.	Send back for repair.
E02	CO ₂ value is under the lower limit.	Recalibrate the CO ₂ . If the error code still appears, send it back for repair.
E03	The CO ₂ reading exceeds the upper limit.	Put the meter in fresh air and wait for 5 minutes. If the error code still appears, recalibrate the meter.
E17	The ABC mode of the CO ₂ sensor fails and might cause wrong CO ₂ readings.	Send the meter back for repair.

9.2 Air Temperature Readings

Error Code	Problem	Solution
E02	The air temperature value is under the lower limit.	Put the meter in regular room temperature for 30 minutes, if the error message still appears, send the device for repair.
E03	The air temperature value exceeds the upper limit.	Put the meter in regular room temperature for 30 minutes, if the error message still appears, send the device for repair.
E31	The temperature sensor or measuring circuit is damaged.	Send the device for repair.

9.3 Air Humidity Reading

Error Code	Problem	Solution
E04	The air temperature measurement has an error code.	Refer to the above mentioned temperature error code.
E11	The RH calibration has failed.	Send the meter back for recalibration.
E34	The RH sensor or the measuring circuit is damaged.	Send the meter back for repair.

10 Warranty and Service

10.1 Warranty

Each Wöhler CDL 210 will be tested in all functions and will leave our factory only after extensive quality control testing.

If used properly, the warranty period for the CDL 210 will be 12 month from the date of sale. Not covered by the warranty are the costs for transport and package.

Service by non authorized personnel or making modifications to the meter voids any warranty.

10.2 Service

We see **SERVICE** as a very important element in our business. That is why we are still available to you even after the guarantee period has expired.

- An **immediate repair** will be carried out if you bring your meter to one of our approved service centers listed below.
- You can obtain **immediate help** from our engineers by telephone.

11 Declaration of Conformity

The product:

Name: CO₂-Logger

Model: CDL 210

has been tested in accordance to essential protection requirements of Council Directive 2004/108/EC and found the test results indeed meet the limitation of the relevant test standards listed below:

EN 61326-1:2006

(CISPR11, IEC/EN 61000-3-2 (2006), IEC/EN 61000-3-3 (2008)

(IEC/EN61000-4-2 (1995+A1:1998+A2:2001)/-3 (2006+A1:2008)

-4(2004)/-5(2006)//-6(2007)/-11(2004))

Points of sale and service

Germany

D79 8 Yi hgW `UbX'; a V<

Im Langel 4

59872 Meschede

Tel.: +49 2903 976 990

Fax: +49 2903 976 9929

info@pce-instruments.com

<http://www.pce-instruments.com/deutsch/>

International

I b]hX' ?]b[Xca

PCE Instruments UK Ltd.

South Point Business Park,

Ensign Way Units 12/13

SO31 4RF Southampton

Tel.: +44 2380 987 03 0

Fax.: +44 2380 987 03 9

<http://www.pce-instruments.com/english/> info@pce-iberica.es

Spain

PCE Iberica S.L.

Calle Mayor 53

302500 Tobarra

Tel.: +34 902 044 604

Fax: +34 967 543 542

Italy

PCE Italia s.r.l.

Via Pesciatina 878 / B-Interno 6

55010 LOC. GRAGNANO -

CAPANNORI (LUCCA)

Tel.: +39 0583 975 114

Fax: +39 0583 974 824

<http://www.pce-instruments.com/italiano/>

France

PCE Instruments France EURL

76, Rue de la Plaine des Bouchers

67100 Strasbourg

Tel. : +33 (0) 972 3537 17

Fax : +33 (0) 972 3537 18

info@pce-france.fr

<http://www.pce-instruments.com/french/>

Your contact: